2021 Shutesbury Annual Operating Report



Timothy Garcia Business Manager <u>Timothy.Garcia@nexteraenergy.com</u>

Joel Walker Site Manager Joel.Walker@nexteraenergy.com

Operation Conditions:

1. Should any segment of the perimeter fencing be visible in winter from Reed Road, that visible portion shall be dark green or black in color.

Response: Perimeter fencing is not visible during the winter from Reed Road.

2. Signage shall be provided to identify the operator of the facility and provide a 24-hour emergency contact phone number. Signage at the perimeter fence warning pedestrians is allowable. Signage shall not be used for displaying any advertising.

Response: There is signage at the site's gate that provides a pedestrian warning as well as the name of the operator and the 24/7 emergency contact phone number.



3. A copy of a final Commissioning Report shall be submitted to the Shutesbury Board of Selectmen no less than 30 days following the activation of the facility.

Response: A copy of the Commissioning Report was provided as part of the 2020 Annual report.

4. Emergency Preparedness: Applicant shall provide a copy of the Project summary, electrical schematic, and site plan to the Fire Chief, Highway Superintendent, and Emergency Management Director, and identify a responsible owner/operator for public inquiries throughout the life of the installation prior to the commencement of the operation of the Project. Signage shall be attached to the gate providing the emergency contact information and the responsible person. The Fire Department shall be provided with a means to open the gate on the access road to the security fencing around the array and shall have access to emergency shut-offs for the solar array. The project operators shall provide a training session for the Fire Department and other Town officials responsible for emergency response on how to use the emergency cutoff switches, and other operational details.

Response:The training for the Fire Department and Town Officials was completed Q3 2021. The Fire Department has installed their own locks on the gates and has the ability to access the site in case of an emergency. They also have been trained in proper shut offs for the solar array.

5. The owner or operator of the project shall submit an annual report demonstrating and certifying compliance with an Operation and Maintenance Plan and the approved special permit, including but not limited to compliance with the approved plans and any special permit conditions, continuation of liability insurance, and adequacy of emergency access. The annual report shall also provide information on the maintenance completed during the course of the year, the status of the wildflower meadow planted in and around the arrays, and the amount of electricity generated by the facility. The report shall be submitted to the Planning Board, Select Board, Fire Chief, Emergency Management Director, and Building Inspector no later than 45 days after the end of the calendar year.

Response: Maintenance completed during 2021:

| ompleted 🖵 | Name | Status | Request Description |
|--------------|--|-----------|---|
| February-21 | Breakdown - Major-Shutesbury - Inv's curtailing, site down prod | Completed | All three inverters were curtailing to about 592kW for at least most of the day on 1/24 and 1/25 with the DAS providing a '523 - TMEiC Inverter Alert (Samurai) - Low Internal Temperature' alert. The cause o the breakdown is unknown. The site stopped producing at ~2:45PM on 1/26/2021 with no system wide alerts triggered, likely weather (snow) related. |
| Echrupry 21 | Snow Removal-Shutesbury | Completed | Snow plow the access road to Pad 2 to support NextEra site work |
| February-21 | Show Removal-Shulesbury | Completed | All phase voltages fell to zero across all meters at ~10:45PM on |
| March-21 | Breakdown - Major-Shutesbury - SEL trip/site down | Completed | 3/1/2021. SEL opened at this time and UPS battery activated. Additionally, all inverters, combiner boxes, and meters for Pads 2 and 3 stopped communicating. |
| April-21 | Breakdown - Major-Shutesbury - All Inv no prod | Completed | All inverters failed to energize on 4/16/2021. The DAS did not provide a fault code. Per wunderground.com, snow was recorded all day long. |
| May-21 | Corrective Maintenance-Shutesbury | Completed | Temporary Antenna |
| June-21 | Breakdown - Partial-Shutesbury - Inv 2 & 3 Under, Inv 1 Over perf | Completed | TMEIC 1.5 MW Inverters 2 and 3 are hitting a max power of 1350 kW instead of the expected 1500kW. The DAS does not display a fault message for the devices during these times and the cause of the breakdown is unknown. Both inverters also appear to be derating when a "Low internal temp" alarm is present. |
| June-21 | Breakdown - Major-Shutesbury - all invs fault | Completed | TMEIC Inverters 1-3 faulted and de-energized at ~6:30AM on 6/14/2021. DAS displays the alert "Minor Fault Ext Minor Fault - Depending on External Connection of I/O PCB" for Inverters 1 and 3. |
| July-21 | Special Project-Shutesbury | Completed | Fire Dept. Training |
| August-21 | Data Communications-Shutesbury - Offtaker No Comms | Completed | Offtaker device stopped reporting to the DAS at ~6:01 PM on 5/20/2021. The DAS gives a "Data communication" alert for this issue. The cause of the breakdown is unknown. |
| September-21 | Site Tour with Town | Completed | Site tour and site cleanup for tour |
| September-21 | Corrective Maintenance-Shutesbury | Completed | Inspect/Repair issues found during Raptor Maps inspection. |
| November-21 | Breakdown - Major-Shutesbury - SEL open/site down | Completed | SEL 351 began reporting "Tripped" status at ~9:15AM on 11/23/2021. All inverters stopped reporting and the site stopped producing at this time. Recloser reset in evening and site RTS |
| December-21 | 2021 Preventative Maintenance Inspection | Completed | Preventative Maintenance Inspection (2021) |
| December-21 | Road Resurfacing | Completed | Resurfacing of entrance road through gate to approximately 200 feet into site. Remainder to be resurfaced in spring |
| December-21 | Corrective Maintenance-Shutesbury | Completed | NEER observed rodent intrusion in Inv.1. Wires have been chewed by the rodents. |
| December-21 | Breakdown - Major-Shutesbury - Inv. 1 Fault | Completed | TMEIC 1500kW inverter 1 faulted and de-energized at ~8:40 AM (MST on 11/30/2021. DAS provided the following alert: "Minor Fault, Ext Minor Fault - Depending on External Connection of I/O PCB". Cause is unknown. |

Energy Production per Month:

| Date | Production Meter Net KWH |
|--------|--------------------------|
| Jan-21 | 245148 |
| Feb-21 | 172727 |
| Mar-21 | 705342 |
| Apr-21 | 699845 |
| May-21 | 830938 |
| Jun-21 | 866192 |
| Jul-21 | 683669 |
| Aug-21 | 705991 |
| Sep-21 | 658555 |
| Oct-21 | 523491 |
| Nov-21 | 406281 |
| Dec-21 | 205478 |

A copy of the certification of liability insurance is included in Appendix A.

6. Applicant shall use only water, and shall not use any soaps, solvents, or other chemicals, in the cleaning of the PV modules.

Response:No module washing has occurred since construction.

7. The project shall have no permanently-affixed exterior lighting.

Response: Project does not have exterior lighting.

8. Herbicide use is prohibited, except in cases of spot treatments to control invasive species, provided only MDAR-approved herbicides as provided on the Sensitive Area Materials list shall be used. Vegetation control shall be by mechanical means. Mowing in and around the solar arrays shall occur no more than once per year, in October or November only. Occasional cutting of plants that shade the solar arrays is permitted provided it is done by a hand-held machine and not by a mower or tractor.

Response: Herbicide is not used on site. Mechanical mowing occurs in October each year and trimming by hand-held machine is completed as needed as vegetation growth impacts production due to shading.

9. All electric power generated at the Project site shall be from solar energy.

Response: All electric power generated at the project is from solar energy.

10. After the completion of construction and site stabilization, the drainage ditches constructed along either side of the access drive between Pratt Corner Road and the first drainage basin shall be top-dressed with a mixture of wood chips and forest soils from the site. Thereafter, the ditches shall be allowed to re-vegetate from ambient seed sources. No mowing or cutting is permitted except for tree cutting and trimming necessary to maintain the serviceability of the access driveway.

Response: The ditches have re-vegetated from ambient seed sources. The ditches are not mowed unless vegetation impedes access to or within the site.

11. The applicant will ensure that initial wildflower meadow plantings installed after construction are stabilized and established sufficiently by any necessary replacement of plants, reseeding, or application of soil amendments for as many growing seasons as is necessary to cover at least 90 percent of the ground surface with either the plants initially installed, native plants that have filled in, or a combination.

Response:The site's near 90 percent ground surface covered with native vegetation. A site clearing (rocks, branches, etc) was completed June of 2021 and will allow greater coverage of growth at the site. The coverage of the vegetation will be observed throughout the summer and a reseeding will occur if needed in the fall to ensure 90 percent coverage is achieved. In September, the vegetation received positive remarks from the Conservation Commission in regard to coverage on the site.



12. All access and internal driveways, fencing, gates, signage, drainage and stormwater infrastructure, solar equipment, and the wildflower meadow shall be maintained and kept in good working order by the owner or operator for the life of the Project.

Response: Due to increased erosion observed in the spring and summer of 2021, Wheelock undertook road repairs and grading on the main access road to ensure it remains in good condition. Wheelock plans to perform more grading and road maintenance in the spring to ensure the longevity of the material. Wheelock will be performing work to ensure the stormwater system is performing as designed, which will include work in the basin and on-site ditches.



Appendix A

| ACORD [®] CERTIFICATE OF LIABILITY INSURANCE | | | | | | | DATE (MM/DD/YYYY) | | | | |
|---|--|------------------|------------|-------------|--|---|----------------------------|----------------------------|--|-----------------------|------------------|
| | | | | | | | | | | 2/2/2022 | |
| | IIS CERTIFICATE IS ISSUED ERTIFICATE DOES NOT AFF | - | | | | | | | | - | - |
| | LOW. THIS CERTIFICATE | | | | | | | | | | |
| | PRESENTATIVE OR PRODU | | | | | / () | | | | | 01110111220 |
| IM | PORTANT: If the certificate | holder | is an | ADD | ITIONAL INSURED, the | olicv(i | es) must ha | | AL INSURED provisi | ons or b | e endorsed. |
| lf \$ | SUBROGATION IS WAIVED, | subject | to th | ne te | rms and conditions of th | e polic | certain p | olicies may | | | |
| | s certificate does not confer | | | | | UCH EN | |). | | | |
| PROD | UCER Beecher Carlson In | suranc | e Se | ervic | es | NAME: | | Brown & Brow | /n FAX | | |
| | a Brown & Brown co 6 Concourse Parkw | ompan /av_Sui | y ite 2 | 300 | | PHONE (A/C, No | o, Ext): | 678-539.4800 |) (A/C, N | <u>o): 7</u> | 70-870-3031 |
| | Atlanta, GA 30328 | ay, ou | | 500 | | E-MAIL ADDRE | SS: | | | | |
| Alama, OA 30320 | | | | | INSURER(S) AFFORDING COVERAGE NAIC # | | | | NAIC # | | |
| www. | bbinsurance.com | | | | | INSURER A : Indemnity Insurance Co of North America 435 | | | | 43575 | |
| | | | ` | | | INSURE | RB: | | | | |
| | G Massachusetts CS 202 extEra Energy, Inc. | zi, LLC | , | | | INSURER C : | | | | | |
| Ne | extEra Energy Resources | s, LLC | | | | INSURER D : | | | | | |
| 70 | 0 Universe Boulevard | | | | | INSURE | RE: | | | | |
| Ju | no Beach FL 33408-265 | 57 | | | | INSURE | RF: | | | | |
| COV | /ERAGES | CER | TIFIC | CATE | E NUMBER: 66579205 | | | | REVISION NUMBER: | | |
| | IS IS TO CERTIFY THAT THE F | | | | | | | | | | |
| | DICATED. NOTWITHSTANDING RTIFICATE MAY BE ISSUED C | | | | | | | | | | |
| | CLUSIONS AND CONDITIONS O | | | | | | | | | IO ALL | THE TERMO, |
| INSR LTR | TYPE OF INSURANCE | | | SUBR WVD | POLICY NUMBER | | POLICY EFF (MM/DD/YYYY) | POLICY EXP (MM/DD/YYYY) | LI | MITS | |
| A | ✓ COMMERCIAL GENERAL LIABIL | ITY | 1 | 1 | CGO G72490678 | | 9/15/2021 | 9/15/2022 | EACH OCCURRENCE | \$5.00 | 00.000 |
| | | 'I IR | • | • | | | | | DAMAGE TO RENTED PREMISES (Ea occurrence) | | 0,000 |
| ŀ | ✓ Time Element Pollution | | | | | | | | MED EXP (Any one person) | \$ 10,0 | |
| ŀ | | | | | | | | | | | |
| ŀ | | | | | | | | | PERSONAL & ADV INJURY | <i>(</i> | 00,000 00,000 |
| ŀ | GEN'L AGGREGATE LIMIT APPLIES P | | | | | | | | GENERAL AGGREGATE | | |
| ŀ | | C | | | | | | | PRODUCTS - COMP/OP AG | <u>G \$5,00</u> \$ | 00,000 |
| | OTHER: AUTOMOBILE LIABILITY | | | | | | | | COMBINED SINGLE LIMIT | \$ | |
| - | | | | | | | | | (Ea accident) | • | |
| - | OWNED SCHEDU | II ED | | | | | | | BODILY INJURY (Per persor | | |
| ŀ | AUTOS ONLY AUTOS HIRED NON-OW | | | | | | | | BODILY INJURY (Per accide PROPERTY DAMAGE | , | |
| - | | | | | | | | | (Per accident) | \$ | |
| | | | | | | | | | | \$ | |
| - | UMBRELLA LIAB OCC | UR | | | | | | | EACH OCCURRENCE | \$ | |
| - | EXCESS LIAB CLAI | IMS-MADE | | | | | | | AGGREGATE | \$ | |
| | DED RETENTION \$ | | | | | | | | | \$ | |
| | WORKERS COMPENSATION AND EMPLOYERS' LIABILITY | V / N | | | | | | | PER OTH STATUTE ER | | |
| | ANYPROPRIETOR/PARTNER/EXECUTIV OFFICER/MEMBER EXCLUDED? | /E Y/N | N/A | | | | | | E.L. EACH ACCIDENT | \$ | |
| | (Mandatory in NH) If ves, describe under | | | | | | | | E.L. DISEASE - EA EMPLOY | EE \$ | |
| | IT yes, describe under DESCRIPTION OF OPERATIONS below | 1 | | | | | | | E.L. DISEASE - POLICY LIM | ΙТ \$ | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| DESC | RIPTION OF OPERATIONS / LOCATION | IS / VEHIC | LES (A | CORE | 0 101, Additional Remarks Schedu | le, may b | e attached if mor | e space is require | ed) | | |
| Poi | Town of Shutesbury Special Pe | ormit | | | | | | | | | |
| See | attached "Additional Remarks | Schedu | ile" fo | r add | litional information. | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| CERTIFICATE HOLDER 0 | | | | | CANCELLATION | | | | | | |
| | | | | | | | | | | | |
| | | | | | | ULD ANY OF | THE ABOVE D | ESCRIBED POLICIES BE | CANCEL | LED BEFORE | |
| Town of Shutesbury PO Box 276 | | | | | | | | EREOF, NOTICE WILL | BE DE | ELIVERED IN | |
| Shutesbury MA 01072 | | | | | ACCORDANCE WITH THE POLICY PROVISIONS. | | | | | | |
| 51 | | | | | | | | | 0 0 0 ° | | |
| | | | | | | | RIZED REPRESE | Bea | echer Carlson Insu | uance Si | ervices, LLC |

| | Beecher Carlson | Insurance | Services, | LLC |
|--|-----------------|-----------|-----------|-----|
|--|-----------------|-----------|-----------|-----|

© 1988-2015 ACORD CORPORATION. All rights reserved.

ACORD 25 (2016/03)

AGENCY CUSTOMER ID:

LOC #:



ADDITIONAL REMARKS SCHEDULE

Page

of

| AGENCY | NAMED INSURED | | |
|------------------------------------|---|-----------------|--|
| Beecher Carlson Insurance Services | DG Massachusetts CS 2021, LLC NextEra Energy, Inc. | | |
| POLICY NUMBER | NextEra Energy Resources, LLC 700 Universe Boulevard | | |
| | Juno Beach FL 33408-2657 | | |
| CARRIER | NAIC CODE | | |
| | | EFFECTIVE DATE: | |

ADDITIONAL REMARKS

THIS ADDITIONAL REMARKS FORM IS A SCHEDULE TO ACORD FORM,

FORM NUMBER: 25 **FORM TITLE:** Certificate of Liability (03/16)

HOLDER: Town of Shutesbury ADDRESS: PO Box 276 Shutesbury MA 01072

Re: Town of Shutesbury Special Permit.

Certificate Holder included as Additional Insured and Waiver of Subrogation applies except where not permissible by law as required by written contract, subject to policy terms, conditions and exclusions.

This insurance is primary and non-contributory over any existing insurance and limited to the liability arising out of the operations of the named insured and where required by written contract.

Severability of interest wording applies to the above policies.

In the event of cancellation by the insurance company, the policy has been endorsed to provide 30 days Notice of Cancellation (except for non-payment) to the certificate holder.